


Hard Wire(HW)



WIRING	
RED	+12VDC Power
BLACK	Ground
YELLOW	Signal (HW)
PURPLE	Signal (chassis)
BLUE	System Status (SYSTAT)